

CARE & MAINTENANCE
Stained wood

Do you need help?

info@out-design.com

+49 30 44 67 38 00

IMPORTANT INFORMATION: The instructions for care and cleaning are only indicative. OBJEKTE UNSERER TAGE disclaims any liability in relation to the use of the following care and cleaning instructions. Any use is at all times at the customer's own responsibility.

GENERAL NOTES

Please note that the care instructions for stained wood surfaces only apply if the surface is undamaged or if there are superficial stains. **OUT OBJEKTE UNSERER TAGE** offers Touch-Up Sticks if the stained surface is damaged. Please contact us for more information.

IMPORTANT NOTE

Never use abrasive cleaners, steel wool or polishing agents.

INDOOR CLIMATE

Caring for wood begins with the right room climate. Both with waxed, stained or lacquered surface finishing. Above all, extreme fluctuations in humidity and temperature, but also a permanently unfavorable room temperature or very dry heating air represents a challenge. Solid wood should not be exposed to this. Because the wood reacts to these influences with shrinkage and swelling, which can lead to warping, shrinkage and fine hairline cracks. Accordingly, a solid wood table should not be placed near a fireplace or heater in order to avoid rapid and drastic fluctuations. The laundry should also not be dried in the same room. A relative humidity of 45% to 60% is recommended, which is also ideal for people. The optimum room temperature

for wood is between 20° and 24°C. In almost all cases, stress cracks are due to “extreme” climatic conditions. Therefore, the room climate, especially humidity and temperature, should be checked regularly. Fine lines and small cracks can occur with stained solid wood tables, but do not further restrict the function. With a constant and appropriate humidity, an optimal wood moisture can be recovered and the process slowed down. With the MEYER Table, the straight rails (in the transverse direction) on the underside of the table top can also be loosened slightly by loosening the screws. This gives the table a little more freedom to react and relieve tension.

DAILY CLEANING

Use a clean and dry cloth to wipe the furniture. For damp cleaning, use a damp cloth that has been wrung out and only do it if absolutely necessary. Do not wipe too wet or with too much pressure. Make sure the cloth is soft so it doesn't damage the surface. For a more thorough cleaning, we recommend a solution of lukewarm water and a mild detergent. Use a soft cloth for this. Dry water and soap residue directly with a dry cloth. Do not use aggressive cleaning agents or abrasive materials such as steel wool. Avoid large amounts of water when cleaning. Wipe up spills immediately. A slight fading of the stained solid oak black over the years is normal. Please never place hot objects such as pots or candles directly on stained surfaces.

**DESIGNED IN BERLIN
MADE IN GERMANY**